

Defect in off road access to Allotment site

Hole in tarmac surface, substructure seems unstable



The map of the extent of the highways that I have been sent by S Barnwell, shows this location to be within the maintained highway. On the south side of Raunds Road, just on the other side of the kerb edging is a tennis ball size hole. The opening, whilst small in itself, has exposed a more extensive unstable area. It is marked by a traffic cone and white spray paint to warn drivers off the area.

The report's reference number is **3806033**. Please quote this if you need to contact the council about this report.

Thank you for your enquiry. This location has been inspected by our team. There are currently no defects that meet our investigatory criteria for repair. These levels have been agreed with North Northamptonshire Council. We will continue to monitor the defect via our routine highway safety inspections.

State changed to: Closed

[Northamptonshire Highways](#)